Purchase Numb	per (Section No.)	RR705001	
Office/Division: Address:	Transportation - Divi Bureau of Design ar 2300 South Dirksen Springfield, IL 62764	d Environment Parkway	
Responsible Chi	ef Procurement Office	r: Timothy W. Martin	
Vendor: Address:	CSX Transportation 4901 Belfort Rd Jacksonville, FL 32		<u></u>
Estimated Cost:	166,652.00		
This expenditure	•	ad facilities in coniun	ction with the departme
Necessa highway Program Emerger	ary adjustment of railro project. nmed railroad safety in	nprovements at indivi provements to compl	oction with the departmental locations in the state of th
Necessa highway Program Emerger Commiss	ary adjustment of railro project. Imed railroad safety in ncy crossing/signal im sion Order(s)	nprovements at indivi provements to comply uiring this expenditure	dual locations in the sta y with Illinois Commerc
Necessa highway Program Emerger Commission	ary adjustment of railro project. Imed railroad safety in ncy crossing/signal importances importances requent al/replacement of a cro	nprovements at indivi- provements to comply uiring this expenditure ssing surface at:	dual locations in the sta y with Illinois Commerc e are: US 51 in Sandoval, I
Necessa highway Program Emerger Commission	ary adjustment of railro project. Imed railroad safety in ncy crossing/signal imp sion Order(s) nd circumstances requ	provements at individual provements to comply uiring this expenditure assing surface at:	dual locations in the sta y with Illinois Commerc e are: US 51 in Sandoval, I

and/or _					_ signals at
FAP	Route	322(US 51)	DOT/AAR No.	152 961B	
Marion		_ County	Name of RR CS	SXT	